

KS200 series Quick Start Manual



This manual is applied to KS200A+, KS200A+_SART and KS200B+_N.
After complete all the installation and setup of KS200 series device just simply switch on the unit by pressing the ON/OFF switch on the rear panel of the device.


For KS200B+_N, KS200A+ and KS200A+_SART

Turning Power ON: Press [ON/OFF] to ON direction to turn on the power.

Turning Power OFF: Press [ON/OFF] to OFF direction to turn off the power.

Indicator

RX: Receiver Indicator
TX: Transmitter Indicator
GPS: GPS indicator
POWER: Power Indicator



The AIS SART button on the KS200A+_SART+ is only used to send distress signals in emergencies. When the SART button on the side of the device is pressed, the device will send an AIS SART message, which can be received by all AIS devices. When the danger has passed, you can press the SART button again to restore the normal state.

Note:

Indication	Light	Description
POWER	red, continuously lit	When the device is turned on, the power indicator is solid red
GPS	Orange, blinking	If GPS positioning is unavailable, the Orange LED will flash.
	Green, continuously lit	The GPS positioning success LED is steadily lit Green.
TX	Red, blinking	Transmits a light that flashes when a signal is emitted.
		The Tx indicator flashes at the following intervals. The reporting interval is: Dynamic Ship Data: Boat speed <2kn: 3 minutes Boat speed >2kn: 30 seconds Static vessel data (similar to Category A): 6 minutes.
RX	Green, blinking	The indicator light flashes green when the signal is received.
Reset hotspot		After successfully resetting the hotspot, GPS lights will go off for five seconds. They will then return to normal after five seconds.

For more details please download the full manual through the following two methods:



Scan the QR code

<http://www.onwamarine.com>

② Visit ONWA website